shane.thomas@gmail.com | My Account | Sign out

Web Images Maps News Shopping Gmail more ▼

Google

| Spatching replacing replacement) ROM (flag or bit) (routine subroutine) | Search

Try uppercase "OR" to search for either of two terms. [details]

Web

Results 1 - 10 of about 29,300 for (patching replacing replacement) ROM (flag or bit) (routine subroutine). (0.52 seconds)

Advanced Search

QuickTrap

Isn't it a bad idea to know how one ROM routine (the dispatcher) communicates with all

qtToolStart: ; Beginning of Toolbox trap replacement routines. .

www.mactech.com/articles/mactech/Vol.04/04.03/QuickTrap/index.html - 80k -

Cached - Similar pages - Note this

Method and apparatus for modifying instruction operations in a ...

If there is no flag bit, the process proceeds to step 320, \dots and the MUX enables the routine to generate the required number of replacement instructions. \dots

www.patentstorm.us/patents/6321380-description.html - 41k -

Cached - Similar pages - Note this

Method and apparatus for modifying instruction operations in a ...

means for interpreting said flag bits as replacement instruction flag bits. by a subroutine or handler routine contained outside the processor core. ...

www.freepatentsontine.com/6321380.html - 53k - Cached - Similar pages - Note this

Apple Assembly Line Volume 2 - Issue 11 August, 1982 In This ...

Lines 3400-3700 contain replacement routines for two of the routines in the FLAG 4180 .2 BIT \$C080 Reprotect LC RAM 4190 LDA #\$96 Return with errant ...

linux.cis.monroeccc.edu/~paulrsm/6502/AAL/AAL8208.TXT - 61k -

Cached - Similar pages - Note this

Apple II Programming

If read, it also provides an "any key down" flag in bit 7, with subroutine which is patched with the location of the appropriate routine as required. ...

home.swbell.net/rubywand/csa2pfaq.html - 86k - Cached - Similar pages - Note this

The Tao of Diagnostics

A subroutine to show one digit of a code is simple, and typically takes the ... the trouble you can then patch small test routines into the product's RAM. ...

www.ganssle.com/articles/adiags2.htm - 22k - Cached - Similar pages - Note this

Apple Assembly Line - V5N6 - Mar 1985

The //c and new //e ROMs patch Applesoft so that lower case keywords and The pointer is divided by two, leaving room for a flag bit which tells which ...

www.txbobsc.com/aal/1985/aal8503.html - 79k - Cached - Similar pages - Note this

ТТТТТТТТТТТТДАN-89 Тимомомомомомомомомомомомомом Тюд...

Here I want to mention the obvious idea of simply modifying or replacing the ROMs in a standard Cellular Phone, and disassembling the ROM software that ...

standard Cellular Phone, and disassembling the HOM software that ... www.hackcanada.com/blackcrawl/ceil/fexts/dnabox.bt - 48k -

Cached - Similar pages - Note this

Statistics - Sameth Seaters - Districtions

[PDF] F2MC-16FX FAMILY ALL SERIES INTERRUPTS

File Format: PDF/Adobe Acrobat - View as HTML

execution of interrupt service routine). 4. T. x. Sticky Bit Flag. This bit is used by

logical/arithmetic right shift. operations ...

mcu.emea.fujitsu.com/document/appnotes/Public/

165/tl/mcu-an-300210-e-16fx_lrq/mcu-an-300210-e-v14-16fx_lrq.pdf-

Similar pages - Note this

EEEEEEE KA | EE R R EE K AA | The BITS ArcSIG EE ..

Need subtraction to compensate when writing interrupt routines. Bits 26-31 are the main

status flags: Bit Letter Description --- 26 F

www.chiark.greenend.org.uk/~theom/riscos/decs/ultimate/a252eur2.txt - 42k -

Cached - Similar pages - Note this

12345678910 Next

(patching replacing replacement) ROM (flag or bit) (routine subroutine)

Search within results | Language Tools | Search Tips | Dissatisfied? Help us improve | Try Google Experimental

©2008 Google - Google Home - Advertising Programs - Business Solutions - About Google

1 of 1 4/25/2008 1:52 PM